



ACHTUNG!
Spindel vor dem aufdrehen
der Mutter reinigen und
einölen.

ATTENTION!
Ball screw must be clean and
oiled before the nut is mounted

PN komplett	Motor PN	Spindel 8x2.5 ball screw	Kugelumlaufmutter ball nut	Bemerkungen remarks
M143208	M136109	Steinmeyer	M134514 (M14x1)	IP40, less items 4,5 and 6
M136110	M136108	SKF	M134516 (M15x1)	IP40, less items 4,5 and 6
M344299	M328091	Eichenberger	M328079 (M15x1)	IP40
M341740	M340446	Eichenberger	M328079 (M15x1)	IP64, less items 4,5 and 6
M353007	M352819	Eichenberger	M328079 (M15x1)	IP40, less items 4,5 and 6
M344299	DPP14 T-10-001Z	Eichenberger	M328079 (M15x1)	IP40

Zul. Abweichung nach DIN ISO 2768 T1-m- DIN ISO 2768 T2-K- Oberflächen nach DIN ISO 1302					Benennung DC - MOTOR/TACHO - ASSEMBLY DC - MOTOR/TACHO - EINHEIT			
Referenz-Zeichnung	Gewicht kg				Format A3	Maßstab 1:1	Maßeinheit mm	Key
CAD-System AutoCAD 2015		Bearb. 27.10.1993	D. Strack	009	Electro-Craft ergänzt		01.02.2016	dschaeffe
		Gepr.		008	thrust block ergänzt		02.09.2015	dschaeffe